

FEB 05 2010

Environmental
Cleanup Office

DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

February 4, 2010

Mr. Michael Sibley U.S. Environmental Protection Agency US EPA Region 10 ECL-116 1200 6th Avenue, Suite 900 Seattle, WA 98101

Re: Request for EPA to mitigate PCB contamination in the 24 inch Stormwater Line at Jorgensen Forge located at 8531 East Marginal Way South, Seattle, Washington.

Dear Mr. Sibley,

The Washington State Department of Ecology (Ecology) requests that you mitigate the PCB contamination in the 24 inch stormwater line located at the Jorgensen Forge Corporation site.

The 24 inch stormwater line is contaminated with PCBs and other contaminants which pose a threat to the Lower Duwamish Waterway by causing environmental damage and posing a risk to human health.

Ecology is unable to accomplish the mitigation task primarily because:

- Current severe budget constraints
- The mitigation requires immediate action without being ensnarled in a legal battle

While Ecology has clear legal authority to compel Jorgensen Forge to clean up the 24 inch stormwater line it is likely that the process could take a long time. Ecology feels that Jorgensen Forge would tie this project up in legal arguments before they cooperated in a cleanup of the 24 inch line. They believe that the pollution in the 24 inch line came from the adjacent Boeing facility, and that are being unfairly asked to shoulder the burden of the cleanup. They could appeal as innocent purchasers or as the victims of third party actions as provided for under Chapter 70.105D RCW. Currently Ecology doesn't have the "creditable evidence" required by Chapter 173-340 WAC to name Boeing as a PLP (same as PRP).

Ecology authority under water quality law is similarly limited because ownership of the stormwater line is unclear as is the list of its operators.





February 4, 2010 Page 2

Ecology Spills Program may have authority, but they currently do not have funds to take on a project as large as the 24 inch stormwater line. Thank you for your interest in assisting with the mitigation of this stormwater line. Please call me at (425) 649-7052 if you have any further questions.

Sincerely,

John Keeling

Toxic Cleanup Program

cc:

Louise Bardy, Ecology Ching-Pi Wang, Ecology Rick Thomas, Ecology

Nels Johnson, AG

Enclosure (1)

RECEIVED

FEB 05 2010

Environmental
Cleanup Office

List of Contacts:

Jorgensen Forge

Mr. Ron Altier Vice President Jorgensen Forge Corporation 8531 East Marginal Way Seattle, WA 98108-4018 (206) 676-9249 raltier@jorgensenforge.com

Ryan Barth
Anchor QEA, LLC
1423 3rd Avenue, Suite 300
Seattle, Washington 98101
(206) 903-3334
rbarth@anchorqea.com

Boeing

William D Ernst
The Boeing Company
P. O. Box 3707-MC1W-12Seattle, WA 98124
(425) 891-7724
william.d.ernst@boeing.com

King County Boeing Field

Peter Dumaliang, Environmental Scientist III Airport Engineering King County International Airport/Boeing Field 7277 Perimeter Rd. S., Seattle WA 98108 Peter.Dumaliang@kingcounty.gov

Direct: (206) 296-7597 Fax: (206) 296-0190 Cell: (206) 391-7577

City of Tukwila

Ryan Larson City of Tukwila Public Works Department 6300 Southcenter Boulevard Tukwila, WA 98188-2544 rlarson@ci.tukwila.wa.us (206) -431-2456